AD-R161 243

USE OF X-RAY RADIOGRAPHIC TECHNIQUES IN THE EVALUATION OF SOIL LINERS(U) ARMY ENGINEER MATERMAYS EXPERIMENT STATION VICKSBURG MS GEOTE. P G MALONE ET AL. SEP 85 NL MES/MP/GL-85-14

MES/MP/GL-85-14

STATION VICKSBURG MS GEOTE. P G MALONE ET AL. SEP 85 NL F/G 8/13

NL FIND

END

END

TORIO

DEND

TORIO

TORIO

DEND

TORIO

TOR



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS - 1963 - A







MISCELLANEOUS PAPER GL-85-14

USE OF X-RAY RADIOGRAPHIC TECHNIQUES IN THE EVALUATION OF SOIL LINERS

by

Philip G. Malone, James H. May

Geotechnical Laboratory

DEPARTMENT OF THE ARMY Waterways Experiment Station, Corps of Engineers PO Box 631, Vicksburg, Mississippi 39180-0631

and

Kirk W. Brown, James C. Thomas Soil and Crop Sciences Department Texas A&M University College Station, Texas 77843



September 1985 Final Report

Approved For Public Release, Distribution Unlimited



Prepared for DEPARTMENT OF THE ARMY Assistant Secretary of the Army (R&D) Washington, DC 20315

> Under Project No. 4A161102A91D Task Area 02, Work Unit 154

OTIC FILE COPY

AD-A161 243

Destroy this report when no longer needed. Do not return it to the originator.

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official endorsement or approval of the use of such commercial products.

Unclassified
SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM			
T REPORT NUMBER 2. GOVT ACCESSION NO.	FECIPIENT'S CATALOG NUMBER			
Miscellaneous Paper GL-85-14 A TITLE (and Substitle)	TYPE OF REPORT & PERIOD COVERED			
USE OF X-RAY RADIOGRAPHIC TECHNIQUES IN THE EVALUATION OF SOIL LINERS	Final report			
EVALUATION OF SOIL LINES	6 PERFORMING ORG. REPORT NUMBER			
7. AUTHOR(a)	B. CONTRACT OR GRANT NUMBER(a)			
Philip G. Malone, Kirk W. Brown, James C. Thomas and James H. May				
9 PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS			
US Army Engineer Waterways Experiment Station Geotechnical Laboratory, PO Box 631, Vicksburg,	Project No. 4A161102A91D			
Mississippi 39180-0631 and Texas A&M University	Task Area 02, Work Unit 154			
Soil and Crop Sciences Department, College Station, Texas 77843	12. REPORT DATE			
11. CONTROLLING OFFICE NAME AND ADDRESS	September 1985			
DEPARTMENT OF THE ARMY Assistant Secretary of the Army (R&D)	69			
Washington, DC 20315	15 SECUPITY CLASS, 'of this report'			
14 MONITORING AGENCY NAME & ADDRESS/II different from Controlling Office)	Unclassified			
	150 DECLASSIFICATION DOWNGRADING SCHEDULE			
16 DISTRIBUTION STATEMENT (of thie Report)				
Approved for public release; distribution unlimited				
17. DISTRIBUTION STATEMENT (of the abetract entered in Block 20, If different from	m Report)			
18. SUPPLEMENTARY NOTES	5005 5 1 5 1 5 1			
Available from National Technical Information Service, 5285 Port Royal Road, Springfield, Virginia 22161.				
19 KEY WORDS (Continue on reverse side if necessary and identify by block number)				
Clay Waste				
Landfill X-ray Liners				
Soil				
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)				
A preliminary study was undertaken to determine the usefulness of soil X-ray radiographic techniques and radio-opaque permeants in testing compacted clay liners used for waste containment. Two methods of using X-ray techniques were examined: one method involved intermittent examination of a test cell during permeation; a second method involved preparing X-radiographs of whole or sliced specimens of simulated liners after they had been subjected to				

DO FORM 1473 EDITION OF ! NOV 65 IS OBSOLETE

permeameter testing.

Unclassified
SECURITY CLASSIFICATION OF THIS PA .E (When Data Entered)

/(Continued)

20. ABSTRACT (Continued).

X-radiographs taken during permeation of a bentonite/sand liner permitted documentation of the progressive invasion of the liner and the development of changes in liner structure (formation of channels or voids). A radio-opaque permeant ($Pb(NO_3)_2$) proved useful for following liquid movement, but was not necessary if only structural changes in the liner were being investigated.

X-radiographs prepared from whole or sliced samples of simulated liners after permeability testing provided data on the homogeneity of the sample, production of open flow paths in the sample, uneven infiltration of the permeating liquid, and the occurrence of surface plugging from suspended solids and side wall leakage. Precipitates forming in the liner could also be observed. The X-ray technique was evaluated with four different types of compacted clay soil liners and five permeating liquids—three aqueous solutions and two suspensions in organic solvents. The radio-opaque compounds used as tracers were $Pb(NO_3)_2$, $Pb(C_2H_3O_2)_2$, and Pb_3O_4 .

Using soil X-ray techniques to follow fluid movement during permeability testing or using X-rays to examine soil samples after permeability testing allows the investigator to check the uniformity of test samples and the performance of the test equipment and to obtain a better understanding of liner/liquid interactions. A thorough testing program can combine both X-ray examination during and after testing.


Further research in this area should include comparison of the performance of permeability test apparatus and development of techniques for the examination of samples of liner material or slurry wall collected by coring field installations. X-ray techniques should also be adapted to examine the effects of chemically reactive liners. Development of organic solvent-based radio-opaque tracers would allow expanded testing of liner/organic waste interaction.

PREFACE

This project was supported as an In-House Laboratory Independent Research (ILIR) Project under Project No. 4A161102A91D, Task Area 02, Work Unit 154.

This report was prepared by Dr. Philip G. Malone of the Site Characterization Unit (SCU) and Mr. James H. May, Chief, SCU, Engineering Geology Applications Group (EGAG), Engineering Geology and Rock Mechanics Division (EGRMD), Geotechnical Laboratory (GL), US Army Engineer Waterways Experiment Station (WES) and Dr. Kirk W. Brown and Mr. James C. Thomas of the Soil and Crop Sciences Department, Texas A&M University. Texas A&M University performed all of the permeability testing, under Purchase Order No. DACA39-84-M-1064. X-ray radiographs were prepared by Mr. Thomas Harmon of the SCU. Mr. Scott Murrell, SCU, assisted in the preparation of photos and drawings. The X-ray diffraction analysis was performed by Mr. J. Pete Burkes, Mmes. Elizabeth E. Odell, Joyce C. Ahlvin and Mr. G. S. Wong of Structures Laboratory. Immediate supervisor on the project was Mr. John H. Shamburger, Chief, EGAG. General supervision was provided by Dr. Don C. Banks, Chief, EGRMD, and Dr. William F. Marcuson III, Chief, GL.

During the preparation of this report, COL Tilford C. Creel, CE, and COL Robert C. Lee, CE, were Commanders and Directors of WES; Mr. F. R. Brown was Technical Director. At the time of publication, COL Allen F. Grum, USA, was Director of WES; Dr. Robert W. Whalin was Technical Director.





CONTENTS

			Page
PREF!	ACE	• • • • • • • • • • • • • • • • • • • •	1
PART	I:	INTRODUCTION	3
		kgroundpose and Scope	
PART	II:	TEST METHODS AND MATERIALS	6
		l-time Liner Tests	
PART	III:	TEST RESULTS AND DISCUSSION	14
		l-time Liner Test Results	
PART	IV:	CONCLUSIONS AND RECOMMENDATIONS	54
		clusionsommendations	
REFE	RENCE	S	55
APPE	NDIX	A: RESULTS OF PERMEABILITY TESTING	A 1

USE OF X-RAY RADIOGRAPHIC TECHNIQUES IN THE EVALUATION OF SOIL LINERS

PART I: INTRODUCTION

Background

- 1. Compacted or amended soils have been widely employed as containment barriers in the storage, treatment or disposal of a wide variety of liquids or leachates from solids (US EPA 1983). In cases where a impounded liquid is a threat to the quality of local ground water (for example, salt water or sewage), the integrity of the liner has been a major consideration in impoundment design. Modern solid waste landfills do not accept liquid wastes, but the liner requirements are often a major engineering concern because precipitation percolating through the landfill cap and contacting the waste can become contaminated and the liner is the principal barrier that prevents the contaminated water from mixing with local ground water.
- 2. Soils employed in liners may be very slowly permeable when placed, but contact with waste can potentially alter the structure of the compacted soil or change the crystal character of individual mineral components and cause the liner to change permeability (Haxo 1978, Brown and Anderson 1983). Laboratory-scale testing using a variety of liquids as permeants has demonstrated that the permeability changes can result from: (a) solution of mineral particles in the liner; (b) piping of fine particles out of the liner; (c) changes in the structure of the clay liner; (d) changes in the crystal structure of minerals in the liner (Acar, Oliveri, and Field 1984; Anderson and Brown 1981; Anderson, Brown, and Green 1981, 1982; Brown, Thomas, and Green 1984; Evans and Fang 1985; Foreman and Daniel 1984; Daniel 1984; Green, Lee, Jones, and Palit 1983).
- 3. Slurry walls are similar in purpose and component materials to liners. A slurry wall is a vertical ground water barrier formed by mixing a graded soil in a bentonite slurry-filled trench. The problems of waste/soil interaction are similar for both barriers and liners and testing procedures for clay-soil mixes employed in both structures are identical (Anderson, Crawley, and Zebcik 1984; Anderson and Jones 1983; US EPA 1984).
 - 4. Clay liners and bentonite (clay) slurry walls are the critical

features employed in designing many disposal sites and in developing remedial measures (Pacey and Karpinski 1980, Price and Sommerer 1982, US EPA 1983). Failure of clay liners and slurry walls can result in the loss of wastes to the surrounding soil and loss of time and effort involved in construction of these barriers. The barriers are developed to contain wastes indefinitely and even relatively slow degradation of the barrier is considered a serious problem.

- 5. Guidance documents on the design of clay liners and soil-bentonite slurry walls recommend laboratory permeameter tests that employ permeants that are similar in composition to the liquids to be retained (US EPA 1983, 1984). Useful test results can be obtained from a variety of permeameter designs, (e.g., fixed wall or triaxial) if careful attention is paid to the test and the quality control procedures followed in the laboratory (US EPA 1984). For example, errors can arise if preparing or packing the sample is not done correctly or if the sample separates from the side wall or if gas bubbles are generated by the interaction of the permeant and the liner material. If the permeant contains suspended material or precipitates, soil clogging will occur and give false readings.
- 6. X-ray radiography has been used extensively in the study of structures in soil or sediment cores (Krinitzsky 1970). Lamination, varves, crossbedding as well as rock fragments and fossils produce sufficient differences in density to be imaged by X-rays. The problems of examining invaded liner samples are much the same as those encountered with sediment cores. In liner investigations, however, the permeant can be selected to provide enhanced contrast between the constituents in the clay liner and the invading fluid.

Purpose and Scope

Purpose

7. Testing of soils for landfill liners is generally done by packing soil samples in a permeameter and examining changes in permeability as different fluids are added. The results obtained can be influenced by sample preparation and the significance of a change in permeability is difficult to interpret. The purpose of this research was to explore the use of soil X-radiography in determine what changes are occurring or have occurred that increase or decrease the rate of fluid movement in a compacted soil.

Scope

8. This project evaluates the ability of X-ray radiography to monitor the real-time invasion of a simulated liner by examining the effect of a lead nitrate/nitric acid solution on a simulated liner formed from a mixture of a commercial bentonite and sand. The project also assesses the usefulness of X-radiography in studying the effect of laboratory permeameter testing on specific samples by preparing X-radiographs of samples of four soils each of which had been permeated with one of four simulated waste liquids or a control $(0.01\ N\ CasO_4)$ solution. Three replicates were prepared for each soil/permeant pair. In all, 60 permeated samples were prepared and examined using X-ray techniques.

PART II: TEST METHODS AND MATERIALS

9. To evaluate the ability of X-radiography to follow the movement of a simulated waste into and through a clay layer as permeation occurred, a plastic cell was fabricated and a layer of mixed hydrated bentonite and sand was placed in it. The simulated waste, an acidic lead nitrate solution, was permitted to infiltrate the bentonite/sand layer from above. In a second sequence of tests X-ray radiographs were prepared from soil samples that had been tested using standard permeameter techniques, in order to learn if the radiographs could be used to determine the type of interaction occurring between the soil and the permeant.

Real-time Liner Tests

Test cell design

- 10. A test cell was fabricated from 75-mm (3-inch) ID, schedule 40 polyvinyl chloride (PVC) pipe to hold a 100-mm (4-inch) thick layer of simulated liner made by mixing sand and a commercially prepared bentonite. The test cell consisted of a 320-mm long section of pipe glued to a coupling with a screw-type clean-out plug installed in the bottom. A hole was drilled in the clean-out plug and a pipe nipple was screwed through the hole to provide a drain. A length of flexible PVC tubing attached to the pipe nipple carried the drainage into a plastic reservoir that could hold all of the liquid permeant. A cut-away drawing of the test cell is shown in Figure 1. Simulated clay liner
- 11. A simulated liner was prepared by mixing one part bentonite clay (Aquagel, Baroid Petroleum Services of NL Industries, Houston, Tex.) with four parts by volume of coarse filter sand. The sand and bentonite were throughly mixed in a 3ry condition, then water was added until the bentonite was completely hydrated. The wet mix slowly settled and was allowed to stand in contact with water for 24 hours.
- 12. The bottom of the test cell was packed with dacron filter floss and a 100-mm thick layer of clean filter sand was placed over the dacron filter. Excess water was decanted from the hydrated bentonite/sand mix and a 100-mm thick layer was poured into the test cell over the clean sand layer. Clean water was placed on top of the bentonite/sand layer and allowed to stand for




Figure 1. Cross-section of the test cell used in the real-time liner test

48 hours to verify that no water would drain from the test cell in its initial condition. The water above the simulated liner was decanted prior to the addition of the waste.

Simulated waste

13. A saturated acidic lead nitrate solution was prepared by shaking a 10 percent nitric acid solution over excess reagent-grade, crystalline, lead nitrate. The solution was allowed to stand in contact with solid lead nitrate for 48 hours at room temperature. The saturated acidic solution was decanted and used as the permeant.

Preparation and X-raying of test cell

- 14. The test cell was clamped in a vertical position to a ring stand and the drain tube was connected to the reservoir. The simulated acidic lead nitrate waste was slowly poured into the test cell taking care not to disturb the bentonite/sand liner. The top of the cell was covered with pliable polyethylene film to retard evaporation but was not sealed. The liquid waste was approximate 140 mm (5.5 in.) deep over the simulated liner.
- 15. Radiographs were taken at one- to five-day intervals until the simulated waste penetrated the liner 16 days after initiation of the test. Additional radiographs were taken at one to two-day intervals until the cell was completely empty, 13 days after initial breakthrough was noted. All radiographs were made using a Norelco MG 300 Industrial X-ray system using a 300 kV tungsten target tube. Kodak Industrex M lead pack film was used. The X-ray unit was operated at 290 kV at 11 mA. Exposure times were varied from 1 to 2 minutes. For publication purposes, prints were prepared from the developed X-ray film. In the prints denser areas in the test cell are dark, not light as they would be in a developed X-ray film.

Mineralogical examination of liner

16. After all X-ray radiographs were completed, samples of the bentonite/sand mixture that had been subjected to the lead nitrate solution were collected from the top layer of the test cell. Samples of the liner material as originally prepared had been collected and stored in sealed containers. The before-testing and after-testing samples were examined using X-ray diffraction. All samples were dried and ground to less than 200-mesh (<74 micro-meters) and examined as packed powder on a General Electric Model 700 Diffractometer using CuK radiation. No attempt was made to control the moisture content during analysis.

Soil/Waste Interaction Tests

Preparation of soil

- 17. Four clay-rich soils of different composition that could be compacted to form pond liners were selected for use in this study. The four clay types represented in the soils were: non-calcareous smectite; calcareous smectite; kaolinite; and illite (mica). Table 1 summarizes the techniques employed in characterizing the soils. The major characteristics and the classification and nomenclature of the test soils are summarized in Table 2.
- 18. Ten-centimeter (4-inch) diameter compaction permeameter molds as described by Brown and Anderson (1983) were used for hydraulic conductivity (permeability) measurements (Figure 2). All soils were mixed, brought to optimum water content, and equilibrated overnight prior to compaction. Compaction was done in three equal lifts using 25 blows per lift of a 2.41 kg (5.5 lb) hammer falling 30 cm (12 in.) on a mechanical compactor (Soil Test Model CN 4230, ASTM Procedures 1557; 698). Lifts consisted of 600, 650, 750, and 750 g for the calcareous smectite, noncalcareous smectite, mica, and kaolinite soils, respectively. The compacted samples were 11.6 cm (4.58 in.) in height. The procedures are the same ones used by Brown and Anderson (1983). After compaction, the appropriate permeant was applied to the soil surface and allowed to stand at atmospheric pressure overnight.

Preparation of permeants

19. Five fluids were prepared as experimental permeants (Table 3). A calcium sulfate solution provided a permeability baseline. Acetate and nitrate solutions represented typical acidic wastes. Acetone and xylene were selected because they represent common organic solvents used in painting, printing and metal cleaning operations and would typically be found in waste suspensions. The lead paint pigment was added to provide a radio-opaque tracer that permitted the movement of the suspended solid material to be observed in radiographs. The lead paint pigment used was lead tetroxide, red lead (Pb_3O_4) obtained from lead primer paint.

Test procedures

20. Three replicate samples were tested for each permeant/soil pair for a total of 60 tests. The permeameters were pressurized with clean, compressed air to 207 kPa (30 psi). The increased head was used so the permeability measurements could be completed within a reasonable time.

Table 1
Techniques Employed in Characterizing Soil Samples

Characteristic	Technique	Reference	
Texture	Visual	Day, 1965	
Cation Exchange Capacity	Wet Analysis	Chapman, 1965	
pH and Alkalinity	Electrometric titration	Peech, 1965	
Atterberg Limits		Sowers, 1965	
Mineralogy	X-ray diffraction	Whittig, 1965	

Table 2
Physical and Chemical Characteristics of the Four Soils Studied

		USDA Soil	Series	
Characteristic	Lufkin	Houston Black	Elgin	Ranger Yellow
Major clay mineral present	non-calcareous smectite	calcareous smectite	kaolinite	illite (mica)
Sand (wt %)*	36	6.8	62.8	60.4
Silt (wt %)	27	47.1	13.6	17.6
Clay (wt %)	37	46.1	24.5	22.0
Liquid limit	54.4	50.6	20.5	21.6
Plastic limit	28.1	40.0	14.3	14.1
Dry Density (g/cm³)	1.44	1.34	1.90	1.98
Cation Exchange Capacity (meq/100g)	24.2	36.8	14.1	14.9
Alkalinity (ppm)	3.3	129.2		
рН	6.1	7.9	7.7	8.0
Mineralogy	QZ-1**	M-1		MI-1
	K-2	K-2	K-1	K-2
	M-2	QZ-3	M-tr	M-3
Source	Brazos Co.,	Bell Co.,	Bastrop Co.,	Eastland Co.,
	Texas	Texas	Texas	Texas
Nomenclature	Vertic	Udic		
	Albaqualfs	Pellusterts		

^{*} Size classification follows Day (1965).

⁹Z = quartz; K - kaolinite; MI = mica; M = montmorillonite. 1 = 340%; 2 = 10-40%; 3 = <10%; tr = trace.




Figure 2. Cross-section of permeameter used in the study of soil/waste interaction

Table 3

Experimental Permeants for Soil/Waste Testing

Test Liquid	Composition		
Water (0.01 N CaSO ₄)	0.068% CaSO ₄		
Lead acetate solution (saturated)	~60% Pb (C ₂ H ₃ O ₂) ₂ *		
Lead nitrate in 0.1% HNO3 (saturated)	~50% Pb (NO ₃) ₂ *		
Acetone containing lead tetroxide	Pb ₃ O ₄ suspension**		
Xylene containing lead tetroxide	Pb ₃ O ₄ suspension**		

After sealing, the cells were not opened until the permeation testing was completed. Leachate was collected daily or more frequently depending on the hydraulic conductivity, and the leachate volume was measured. Hydraulic conductivity was calculated using Darcy's Law in the following form:

$$K = \frac{vl}{A t \Delta h}$$

where

K = hydraulic conductivity, cm/sec

v = volume of liquid passed through the core, cm³

l = length of the soil core, cm

A = cross-sectional area of the soil core, cm^2

t = time, sec

 Δh = difference in hydraulic head between the top and bottom of the soil core, cm of water

21. The hydraulic conductivities obtained with Darcy's law can be normalized for liquids with various viscosities and densities by multiplying by the density and dividing by the viscosity of the permeant. In this report the changes in hydraulic conductivity in a single soil type over the course of a permeability test was the information of interest; therefore the normalization of the data was not needed. The volume discharged from each column was

^{*} Reacts slowly with CO₂ to produce PbCO₃ that is insoluble.

^{**} Approximately 200 to 250 ml of settled paint pigment was added to each 600 ml aliquot of xylene or acetate used for testing.




Figure 3. Print of radiograph of simulated liner before application of acidic $Pb(NO_3)_2$ solution




Figure 4. Print of radiograph of simulated liner one day after application of acidic $Pb(NO_3)_2$ solution




Figure 5. Print of radiograph of simulated liner 25 days after application of acidic ${\rm Pb}({\rm NO_3})_2$ solution




Figure 6. Comparison of X-ray diffraction traces produced from simulated clay liner before (left trace) and after (right trace) application of acidic Pb(NO₃)₂ solution

materials (such as lead compounds) removes a requirement to make the test permeant different from the actual waste and also eliminates the problem of handling potentially toxic salts (like lead nitrate).

Applications of real-time examination

28. X-ray examination made during permeability testing of liner materials (such as the bentonite/sand mix used here) can provide immediate information on the quality of sample preparation (sample homogeneity and sample packing) and on test equipment performance (leaks and side wall effects). The development of a pattern of fluid movement and changes in liner appearance are helpful in interpreting the mechanisms involved in a liner failure. Where structural changes in liners are being investigated, a radio-opaque tracer is not needed. If fluid movement is a major concern, it should be possible to select stable radio-opaque compounds or radio-opaque organometalic complexes that can be used as tracers.

Soil/Waste Interaction Test Results

29. The results of the permeability tests of the compacted soils with the experimental permeants are summarized in Appendix A. The data on swelling of the soils measured after permeation are presented in Table 4.

Non-calcareous smectite

30. The non-calcareous smectite showed low permeabilities when subjected to the 0.01 N CaSO $_{\rm ll}$ solution. In two replicates (identified as REP 1 and REP 2) the permeability started at 1 × 10⁻⁶ cm/sec and dropped and the third sample (REP 3) showed a very low initial permeability (Figure 7). The decreased permeability with continued flow could be related to the swelling observed in these samples (Table 4). In tests using lead acetate as the permeant a similar low permeability was noted (Figure 8). The radiographs of the samples indicate that lead was interacting with and precipitating in the compacted soil. Figure 9 shows that the non-calcareous smectite developed a precipitate with a fiberous texture, suggesting that lead compounds were precipitating or being absorbed into the liner. Permeability was decreased, but the liner was partly penetrated and had reacted with the permeant. The acidic lead nitrate solution (Figure 10) produced a large increase in permeability (from initial conductivity of 10^{-8} cm/sec to 10^{-6} cm sec). The X-ray examination of the samples showed irregular connecting voids suggesting the clay

Table 4
Soil Swelling in Cores After Permeation with Various Liquids

Permeant	Replicate Number	Non-calcareous Spectite, % Swelling*	Calcareous Smectite, % Swelling	Kaolinite % Swelling	Illite % Swelling
0.01 N CaSO ₄	1	0.8	0	0.9	0
	2	1.5	1.2	0	0.7
	3	0	1.0	0	0
Lead Acetate	1	2.7	2.3	0.6	1.5
	2	2.6	2.2	2.0	1.5
	3	0	2.5	0	1.3
Acetone with lead paint pigment	1	0	0	0	0
	2	0	0	0	0
	3	0	0	0	0
Xylene with lead paint pigment	1	0	0	0	0
	2	0	0	0	0
	3	0	0	0	0
0.1% HNO $_3$ with Pb $(NO_3^3)_2$	1	1.6	2.7	0	0
	2	1.0	2.9	0	0
	3	0.6	2.6	0	2.5

^{* %} swelling is the change in height divided by the original height and multiplied by 100.




Figure 7. Hydraulic conductivity of unsaturated non-calcareous smectite measured using 0.01 N CaSO_{4}




Figure 8. Hydraulic conductivity of unsaturated non-calcareous smectite measured using saturated lead acetate solution



Figure 9. Print of radiograph of non-calcareous smectite soil permeated with lead acetate solution, whole sample, actual size (Replicate 3)




Figure 10. Hydraulic conductivity of unsaturated non-calcareous smectite measured using 0.1% ${\rm HNO_3}$ saturated with Pb ${\rm (NO_3)_2}$

had developed a flocculated (or blocky) structure (Figure 11) similar to the structure that had occurred with the bentonite/sand mixture (which also contained smectite) in the real-time liner failure study (Figure 5). Exposure of the non-calcareous smectite to acetone or xylene suspensions of paint pigment produced very low permeabilities (Figure 12). The radiographs of these samples showed the paint pigments produced a plugging on the soil surface and only minor penetration of the samples occurred (Figure 13).

31. The calcareous smectite showed a typical low $(1 \times 10^{-6} \text{ cm/sec})$ and decreasing permeability when tested with 0.01 N CaSO_H (Figure 14). The appearance of three "lifts" of soil packed during preparation of the samples can be noted in Figure 15 but the samples are relatively featureless. Permeation with lead acetate produced a pronounced reduction in permeability (Figure 16). Radiographs prepared from the lead acetate permeated samples show an irregular darkened pattern indicating precipitation of lead in the sample (Figure 17) and indicate that permeation was not uniform across the entire diameter of the sample. Samples of the calcareous smectite showed an increase in hydraulic conductivity when attacked with the acidic lead nitrate (Figure 18), but the increase was less than that observed in the non-calcareous smectite. Radiographs of the calcareous smectite show a dark pattern indicating lead was deposited in the soil but there is no pronounced change in soil structure (Figure 19), as was observed in the non-calcareous smectite. The samples permeated with paint pigments suspended in acetone showed variable hydraulic conductivities suggesting side wall leakage (Figure 20), but this could not be confirmed from the radiographs. The suspected samples looked similar to plugged samples. If the liquid separates from the suspended lead compounds, liquid movement cannot be traced. Exposure of the samples to suspended paint pigments in xylene resulted in reduced hydraulic conductivities (Figure 21). Radiographs indicated the suspended paint solid plugged the tops of the samples (Figure 22).

Kaolinite

Calcareous smectite

32. The kaolinitic soil showed low hydraulic conductivities $(1 \times 10^{-7} \text{ cm/sec})$ when 0.01 N CaSO₄ was used as a permeant (Figure 23). Lead acetate solution produced no increase in hydraulic conductivity (Figure 24) although the X-ray indicates that lead acetate had invaded the outer section of the permeameter sample (Figure 25). The uneven pattern of lead




Figure 11. Print of radiograph of non-calcareous smectite soil permeated with acidic lead nitrate solution, whole sample, actual size (Replicate 1)




Figure 12. Hydraulic conductivity of unsaturated non-calcareous smectite measured using xylene containing lead paint pigment




Figure 13. Print of radiograph of non-calcareous smectite soil tested with lead paint pigment/xylene suspension, whole sample, actual size (Replicate 1)




Figure 14. Hydraulic conductivity of unsaturated calcareous smectite measured using 0.01 N CaSO $_{\mbox{\sc l}}$




Figure 15. Print of radiograph of calcareous smectitic soil permeated with 0.01 N CaSO $_{\mu}$, whole sample, actual size (Replicate 1)




Figure 16. Hydraulic conductivity of unsaturated calcareous smectite measured using saturated lead acetate solution




Figure 17. Print of radiograph of calcareous smectitic soil permeated with lead acetate solution, sectioned sample, actual size (Replicate 2)




Figure 18. Hydraulic conductivity of unsaturated calcareous smectite measured using 0.1% $\rm HNO_3$ saturated with $\rm Pb(NO_3)_2$




Figure 19. Print of radiograph of calcareous smectitic soil permeated with acidic lead nitrate solution, sectioned sample, actual size (Replicate 3)




Figure 20. Hydraulic conductivity of unsaturated calcareous smectite measured using acetone containing lead paint pigment




Figure 21. Hydraulic conductivity of unsaturated calcareous smectite measured using xylene containing lead paint pigment




Figure 22. Print of radiograph of calcareous smectitic soil tested with lead paint pigment/xylene suspension, sectioned sample, actual size (Replicate 1)




Figure 23. Hydraulic conductivity of unsaturated kaolinitic soil measured using 0.01 N ${\rm CaSO}_{4}$




Figure 24. Hydraulic conductivity of unsaturated kaolinitic soil measured using a saturated lead acetate solution




Figure 25. Print of radiograph of kaolinitic soil permeated with lead acetate solution, sectioned sample, actual size (Replicate 1)

precipitation in the radiograph indicates initial leakage along the side walls with precipitation of lead compounds producing a tighter seal. Exposure to the acidic lead nitrate solution increased the conductivity to 1×10^{-6} cm/sec and above (Figure 26). The radiographs of the soil (Figure 27) showed uneven invasion of the lead nitrate with flow along the side walls and extensive precipitation of lead along the bottom of the permeameter sample. Both suspended lead paint pigments produced clogging in the samples and the permeabilities dropped into the range 1×10^{-8} to 2×10^{-9} cm sec (Figures 28 and 29). Illite

33. The illitic or micaceous soil had a hydraulic conductivity of 1×10^{-8} cm/sec when 0.01 CaSO $_{\rm ll}$ was used as a permeant (Figure 30). The lead acetate solution produced similar hydraulic conductivities (Figure 31), but the radiographs prepared from the lead acetate-permeated samples show that the lead solution had precipitated in the upper parts of the soil samples (Figure 32). Although the hydraulic conductivity did not change, the soil showed strong interaction with the permeant. The exposure to the acidic lead nitrate increased the hydraulic conductivity initially with the hydraulic conductivity later decreasing (Figure 33). The radiographs prepared from the soil sample showed that permeation of the nitric acid was uneven with most extensive invasion in the center of the sample with uninvaded areas along the side walls (Figure 34). The lead precipitating in the soil may have produced clogging. The suspended paint pigments produced a slight increase in conductivity but the paint pigments clogged the soil surface to reduce any change in conductivity (Figures 35 and 36).

Application of post-testing examination

34. The X-ray examination of the samples after permeation was helpful in understanding the results obtained from hydraulic conductivity testing and for showing the changes in the soil structure that indicate a liner failure will occur. For example, Figure 10 shows that lead nitrate produced a 100-fold increase in hydraulic conductivity in the non-calcareous smectite (replicate 1) and the radiograph confirms that the structure of the clay is thoroughly altered. Replicates 2 and 3 showed smaller increases in hydraulic conductivity but the alteration at the top of these samples is similar to changes observed in replicate 1 (Figure 11). The X-ray examination suggested replicates 2 and 3 could be easily altered to become as permeable as replicate 1, if testing had continued.




Figure 26. Hydraulic conductivity of unsaturated kaolinitic soil to 0.1% $\rm HNO_3$ saturated with $\rm Pb(NO_3)_2$



Figure 27. Print of radiograph of kaolinitic soil permeated with acidic lead nitrate solution, sectioned sample, actual size (Replicate 2)




Figure 28. Hydraulic conductivity of unsaturated kaolinitic soil measured using acetone containing lead paint pigment at a gradient of 181




Figure 29. Hydraulic conductivity of unsaturated kaolinitic soil measured using xylene containing lead paint pigment




Figure 30. Hydraulic conductivity of unsaturated illitic soil measured using 0.01 N CaSO_{4}




Figure 31. Hydraulic conductivities of unsaturated illitic soil measured using a saturated lead acetate solution




Figure 32. Print of radiograph of illitic soil permeated with lead acetate solution, whole sample, actual size (Replicate 1)




Figure 33. Hydraulic conductivity of unsaturated micaceous soil to 0.1% measured using ${\rm HNO_3}$ saturated with ${\rm Pb(NO_3)_2}$




Figure 34. Print of radiograph of illitic soil permeated with acidic lead nitrate solution, section sample, actual size (Replicate 1)




Figure 35. Hydraulic conductivity of unsaturated illitic soil measured using acetone containing lead paint pigment




Figure 36. Hydraulic conductivity of unsaturated illitic soil measured using xylene containing lead paint pigment

35. X-ray examination often indicated that interaction between the liner and the liquid occurred when the permeability measurement showed little difference. For example, in the illitic soil, the hydraulic conductivities (Figures 30 and 31) recorded for the permeants, 0.01 N CaSO $_{\parallel}$ and lead acetate are both low (near 10^{-8} cm/sec). The soil did, however, swell 1.5% (Table 4) when lead acetate was used as a permeant. X-ray examination of the sample shows that precipitation of lead had occurred through the entire top of the simulated liner (Figure 32) and more swelling could be expected if the precipitation continued. X-ray radiographs prepared during permeation are valuable for demonstrating liner changes but examination of sample after permeation is also helpful in confirming suspected changes or indicating interaction not evident from other measurements.

PART IV: CONCLUSIONS AND RECOMMENDATIONS

Conclusions

- 36. X-radiography of soil samples can provide useful information on alteration in soil structure and on patterns of fluid penetration during hydraulic conductivity testing. X-ray examination of test samples offers numerous advantages:
 - <u>a</u>. Voids or cracks produced by changes in soil structure can be readily identified.
 - b. Local precipitation of waste constituents in the soil can be detected if the precipitates are dense enough to provide contrast in the X-ray.
 - c. Changes in the liners which cannot be inferred from hydraulic conductivity measurements can be noted in X-rays.
 - d. Non-uniform soil packing and permeant flow caused by leakage along the sidewall can be detected if the permeant contains soluble radio-opaque compounds.
 - e. Inspection of samples using X-ray can be performed during permeation or on samples after hydraulic conductivity measurements are complete to provide verification of test performance.
 - $\underline{\mathbf{f}}$. Simulated liners inspected during low-gradient experimental interaction with waste can be used to estimate the speed with which a particular type of waste can penetrate a liner.

Recommendations

- 37. Additional studies should be conducted with X-radiography to advance our techniques for laboratory-based liner testing and inspection of samples from waste sites. The studies should include:
 - <u>a</u>. Fixed wall and triaxial hydraulic conductivity testing systems should be examined with X-ray while in operation to determine the extent and effect of problems with sample preparation and the effect of rigid or flexible sidewalls on fluid flow.
 - b. X-ray examination should be applied to core samples from failed and properly functioning clay liner or slurry-wall materials to establish the extent and mode of failure.
 - c. Liners containing lime or other buffering materials should be examined using X-ray techniques to demonstrate the effects of chemically reactive barriers in protecting liners.
 - d. Organic-metal complexes (like tetraethyl lead) should be developed for use as tracers to obtain data on movement of organic wastes in liner materials.

REFERENCES

- Acar, Y. B., Oliveri, I., and Field, S. D. 1984. "Organic Fluid Effects on the Structural Stability of Compacted Kaolinite," <u>Proceedings of the Tenth Annual Research Symposium</u>, EPA-600/9-84-007, US Environmental Protection Agency, Cincinnati, Ohio, pp 162-171.
- Anderson, D., and Brown, K. W. 1981. "Organic Leachate Effects on the Permeability of Clay Liners," <u>Proceedings of the Seventh Annual Research Symposium</u>, EPA-600/9-81-0026, US Environmental Protection Agency, Cincinnati, Ohio, pp 119-130.
- Anderson, D. C., Brown, K. W., and Green, J. 1981. "Organic Leachate Effects on the Permeability of Clay Liners," <u>Proceedings of Conference on Management of Uncontrolled Hazardous Waste Sites</u>, Hazardous Materials Control Research Institute, Silver Springs, Md., pp 223-229.
- . 1982. "Effect of Organic Fluids on the Permeability of Clay Soil Liners," Proceedings of the Eighth Annual Research Symposium, EPA-600/9-82-002, US Environmental Protection Agency, Cincinnati, Ohio, pp 179-190.
- Anderson, D. C., and Jones, S. G. 1983 "Clay Barrier-Leachate Interactions," Proceedings of the National Conference on Management of Uncontrolled Hazardous Waste Sites (1983), Hazardous Materials Control Research Institute, Silver Springs, Md., pp 154-161.
- Anderson, D. C., Crawley, W., and Zabcik, D. 1984. "Effects of Various Liquids on Clay Soil-Bentonite Slurry Mixtures," K. W. Brown and Associates, Inc., College Station, Tex.
- Brown, K. W., and Anderson, D. C. 1983. "Effects of Organic Solvents on the Permeability of Clay Soils," EPA-600/2-83-016, US Environmental Protection Agency, Cincinnati, Ohio.
- Brown, K. W., Thomas, J. C., and Green, J. W. 1984. "Permeability of Compacted Soils to Solvent Mixtures and Petroleum Products," <u>Proceedings of the Tenth Annual Research Symposium</u>, EPA-600/9-84-007, US Environmental Protection Agency, Cincinnati, Ohio, pp 124-137.
- Chapman, H. B. 1965. "Cation Exchange Capacity," Methods of Soil Analysis, C. A. Black, ed., Part 1, pp 891-900, American Society of Agronomy, Inc., Madison, Wisc.
- Daniel, D. E. 1984. "Predicting Hydraulic Conductivity of Clay Liners," <u>Journal of Geotechnical Engineering</u>, Vol 110, No. 2, pp 285-300.
- Day, P. R. 1965. "Particle Fractionation and Particle Size Analysis," Methods of Soil Analysis, C. A. Black, ed., Part 1, pp 545-546, American Society of Agronomy, Inc., Madison, Wisc.
- Evans, J. C., and Fang, H-Y. 1985. "Organic Fluids Effects on the Permeability of Soil-Bentonite Slurry Walls," Woodward-Clyde Consultants, Plymouth Meeting, Pa., draft, unpaginated.
- Foreman, D. E., and Daniel, D. E. 1984. "Effects of Hydraulic Gradient and Method of Testing on the Hydraulic Conductivity of Compacted Clay to Water, Methanol, and Heptane," <u>Proceedings of the Tenth Annual Research Symposium</u>, EPA-600/9-84-007, US Environmental Protection Agency, Cincinnati, Ohio, pp 138-144.

- Green, W. J., Lee, G. F., Jones, R. A., and Palit, T. 1983. "Interaction of Clay Soils with Water and Organic Solvents: Implications for the Disposal of Hazardous Wastes," <u>Environmental Science and Technology</u>, Vol 17, pp 278-282.
- Haxo, H. E., Jr. 1978. "Interaction of Selected Lining with Various Hazardous Wastes," <u>Proceedings of the Fourth Annual Research Symposium on Land Disposal of Hazardous Wastes</u>, EPA-600/9-78-016, US Environmental Protection Agency, Cincinnati, Ohio, pp 256-272.
- Krinitzsky, E. L. 1970. <u>Radiography in the Earth Sciences and Soil Mechanics</u>, Plenum Press, New York.
- Pacey, J., and Karpinski, G. 1980. "Selecting a Landfill Liner," <u>Waste Age</u>, Vol 11, No. 7, pp 26-28.
- Peech, M. 1965. "Hydrogen Ion Activity," Methods of Soil Analysis, C. A. Black, ed., pp 919-925, American Society of Agronomy, Inc., Madison, Wisc.
- Price, D. A., and Sommerer, S. 1982. "Engineering and Development Support of General Decon Technology for the US Army's Installation Restoration Program; Task 7, Literature Search and Evaluation of Compactibility Testing of Waste Containment Barrier Materials," Report No. 49-5002-07-0001, US Army Toxic and Hazardous Materials Agency, Aberdeen, Md.
- Sowers, G. F. 1965. "Consistency," <u>Methods of Soil Analysis</u>, C. A. Black, ed., pp 391-399, American Society of Agronomy, Inc., Madison, Wisc.
- US Environmental Protection Agency. 1983. "Lining of Waste Impoundments and Disposal Facilities," SW-870, Washington, DC.
- . 1984. "Slurry Trench Construction for Pollution Migration Control," EPA 540/2-84-001, Washington, DC.
- Whittig, L. D. 1965. "X-ray Diffraction Techniques for Mineral Identification and Mineralogical Comparison," <u>Methods of Soil Analysis</u>, C. A. Black, ed., Part 1, pp 671-696, American Society of Agronomy, Inc., Madison, Wisc.

APPENDIX A
RESULTS OF PERMEABILITY TESTING

Repl:	icate 1	Rep1	icate 2	Repli	cate 3
Pore Volume	Ave K	Pore Volume	Ave K	Pore Volume	Ave K
			<0.1	9.47E-8	0
			0.2	3.72E-8	
			0.3	2.54E-8	
0.4	1.34E-7	0.4	1.96E-8		
0.7	1.08E-7	0.5	1.91E-8		
0.8	7.06E-8	0.6	1.46E-8		
0.9	5.72E-8				
1.0	5.45E-8				
1.1	4.63E-8				

Table A2

<u>Average Hydraulic Conductivity of Compacted Non-Calcareous</u>

<u>Smectite to a Saturated Solution of Lead Acetate</u>

	icate 1		icate 2		icate 3
Pore Volume	Ave K	Pore <u>Volume</u>	Ave K	Pore <u>Volume</u>	Ave K
<0.1	1.28E-8	<0.1	1.12E-8	0.1	3.23E-8
0.1	1.67E-8	0.1	1.46E-8	0.2	2.27E-8
0.2	1.62E-8	0.2	1.47E-8	0.3	1.57E-8
0.3	8.51E-9	0.3	1.46E-8	0.4	2.69E-8
0.4	6.94E-9	0.4	1.21E-8	0.5	2.47E-8
0.5	6.22E-9	0.5	8.77E-9	0.6	2.28E-8
0.6	5.52E-9	0.6	5.72E-9	0.8	2.26E-8
0.7	5.66E-9	0.7	5.12E-9	0.9	2.37E-8
0.8	4.93E-9	0.8	6.00E-9	1.0	2.60E-8
0.9	5.52E-9	0.9	6.54E-9	1.1	2.35E-8
1.0	5.58E-9	1.0	6.98E-9	1.2	1.74E-8

Table A3

Average Hydrualic Conductivity of Compacted Non-Calcareous

Smectite to 0.1% HNO₃ Saturated with Pb(NO₃)₂

	icate 1		icate 2		icate 3
Pore Volume	Ave K	Pore <u>Volume</u>	Ave K	Pore <u>Volume</u>	Ave K
<0.1	1.18E-8	<0.1	6.83E-9	<0.1	3.84E-9
0.1	1.86E-8	0.1	1.15E-8	0.1	5.90E-9
0.2	1.89E-8	0.2	1.30E-8	0.2	7.46E-9
0.3	1.64E-7	0.3	1.79E-8	0.3	4.86E-8
0.4	2.08E-7	0.4	8.97E-9	0.8	5.82E-8
0.5	4.10E-8	0.5	9.74E-9	1.2	1.01E-7
0.6	5.52E-7	0.6	1.06E-8	1.3	1.12E-7
0.7	1.45E-6	0.7	1.41E-8		
1.2	1.60E-6	0.8	2.72E-8		
1.3	1.64E-6	0.9	2.29E-8		
1.4	1.66E-6	1.0	2.52E-8		
1.6	1.31E-6	1,1	2.40E-8		
		1,2	1.28E-8		

Table A4

Average Hydrualic Conductivity of Compacted Non-Calcareous

Smectite to Acetone Containing Lead Paint Pigment

Replicate 1		Replicate 2		Replicate 3	
Pore Volume	Ave K	Pore Volume	Ave K	Pore Volume	Ave K
<0.1	6.2E-10	0	0		

Table A5

Average Hydraulic Conductivity of Compacted Non-Calcareous

Smectite to Xylene Containing Lead Paint Pigment

Repl	icate 1	Repl	icate 2	Repl	icate 3
Pore		Pore		Pore	
<u>Volume</u>	Ave K	Volume	Ave K	Volume	Ave K
<0.1	3.95E-9	<0.1	3.13E-8	<0.1	5.76E-9
0.1	2.27E-8	0.3	4.10E-8	0.1	1.03E-8
0.2	5.17E-8	0.4	3.17E-8	0.2	1.22E-8
0.3	3.47E-8	0.5	2.74E-8	0.3	1.18E-8
0.5	2.07E-8	0.6	2.24E-8	0.4	1.33E-8
0.6	1.70E-8	0.7	1.70E-8	0.5	1.18E-8
0.7	9.32E-9	0.8	1.53E~8	0.6	7.71E-9
0.8	9.48E-9	0.9	1.43E-8	0.7	5.65E-9
0.9	1.03E-8	1.0	9.23E-9	0.8	1.94E-9
1.0	9.19E-9	1.1	5.92E-9		

Repl	icate 1	Repl	icate 2	Replicate 3	
Pore Volume	Ave K	Pore Volume	Ave K	Pore Volume	Ave K
<0.1 0.1 0.2 0.3 0.4	5.86E-9 1.30E-8 1.62E-8 1.45E-8 1.38E-8	<0.1 0.3 0.4 0.7 0.9 1.0 1.2 1.3 1.4	2.76E-7 2.39E-6 1.74E-6 1.29E-6 9.90E-7 4.78E-7 6.35E-7 2.99E-7 2.36E-7 5.85E-8	0.1 0.2 0.3 0.4 0.9 1.0 1.1	8.02E-7 6.05E-7 4.61E-7 3.86E-7 2.18E-7 2.12E-7 1.74E-7 4.47E-7

Table A7

Average Hydraulic Conductivity of Compacted Calcareous

Smectite to a Saturated Lead Acetate Solution

Repl	icate 1	Repl	icate 2	Repl	icate 3
Pore Volume	Ave K	Pore Volume	Ave K	Pore Volume	_Ave K
		0.1	1.27E-7	0.1	3.61E-7
0.2	1.50E-7	0.2	1.01E-7	0.2	3.97E-7
0.3	2.05E-7	0.3	5.04E-8	0.3	3.06E-7
0.4	1.49E-7	0.4	3.95E-8	0.6	1.03E-7
0.6	8.31E-8	0.5	3.77E-8	0.7	4.42E-8
0.8	6.37E-8	0.6	3.46E-8	0.9	4.26E-8
0.9	6.32E-8	0.7	3.02E-8	0.9	4.02E-8
1.1	5.71E-8			1.0	3.23E-8
1.2	4.18E-8				

Table A8 Average Hydraulic Conductivity of Compacted Calcareous Smectite to 0.1% HNO $_3$ saturated with Pb(NO $_3$) $_2$

Repl	icate 1	Repl	icate 2	Repl	icate 3
Pore		Pore		Pore	
<u>Volume</u>	Ave K	<u>Volume</u>	Ave K	Volume	Ave K
<0.1	2.26E-7				
0.1	2.69E-7			0.1	1.13E-7
0.3	1.44E-7			0.2	8.51E-7
0.4	1.09E-7	0.4	1.30E-6	0.3	1.46E-6
0.6	1.13E-7	0.5	1.50E-6	0.4	9.92E-7
0.7	1.65E-7	0.6	8.22E-7	0.5	7.04E-7
0.8	1.49E-7	0.7	9.62E-7	0.6	5.08E-7
1.0	1.22E-7	0.8	6.08E-7	0.7	2.17E-7
1.1	8.58E-8	0.9	4.15E-7		
1.2	7.58E-8	1.0	2.16E-7		

Table A9

Average Hydraulic Conductivity of Compacted Calcareous Smectite

to Acetone Containing Lead Paint Pigment

Repl	Replicate 1		Replicate 2		Replicate 3	
Pore Volume	Ave K	Pore Volume	Ave K	Pore Volume	Ave K	
0.1	1.95E-6	0.1	2.01E-8	0.00	0	
0.2	4.73E-6	0.2	2.36E-6	0.00	0	
0.3	5.14E-6			0.12	>6.57E-8	
0.4	4.83E-6					
0.5	3.64E-6					
0.6	3.99E-6					
0.7	3.96E-6					
0.8	3.49E-6					
0.9	3.30E-6					

Table A10

Average Hydraulic Conductivity of Compacted Calcareous Smectite

to Xylene Containing Lead Paint Pigment

Repl	icate 1	Repl	icate 2	Replicate 3	
Pore Volume	Ave K	Pore <u>Volume</u>	Ave K	Pore Volume	_Ave K
<0.1	3.09E-8	<0.1	1.53E-8	<0.1	1.88E-9
0.1	3.94E-8	0.1	2.23E-8	0.1	4.27E-8
0.2	3.53E-8	0.2	2.33E-8	0.2	3.66E-8
0.3	2.36E-8	0.3	1.57E-8	0.4	1.88E-8
0.4	2.87E-8	0.4	1.44E-8	0.5	1.30E-8
0.5	1.64E-8	0.5	1.64E-8	0.6	9.61E-9
0.6	1.17E-9	0.6	9.62E-9	0.7	4.83E-9
0.7	5.01E-9	0.7	8.39E-9	0.8	2.98E-9
0.8	1.77E-9	0.8	8.25E-9	0.9	1.61E-9
		0.9	5.45E-9		
		1.0	5.57E-9		

Table A11 Average Hydraulic Conductivity of Compacted Illitic Soil to 0.01 N CaSO $_{\mbox{\scriptsize μ}}$

Repl	Replicate 1		Replicate 2		Replicate 3	
Pore Volume	Ave K	Pore Ave K Volume	Ave K	Pore Volume	Ave K	
				<0.1	2.11E-9	
0.1	9.20E-9	0.00	0	0.1	3.96E-9	
0.2	1.05E-8	1.80	<2.66E-7			
0.3	9.21E-9					
0.5	8.72E-09					
0.6	8.92E-9					

Table A12

Average Hydraulic Conductivity of Compacted Illitic Soil

to a Saturated Lead Acetate Solution

Repl	icate 1	Repl	icate 2	Repl	icate 3
Pore		Pore		Pore	
Volume	Ave K	Volume	Ave K	Volume	Ave K
<0.1	5.17E-9	<0.1	5.01E-9	<0.1	3.95E-9
0.1	7.30E-9	0.1	4.87E-9	0.1	4.71E-9
0.2	8.02E-9	0.2	4.00E-9	0.2	5.15E-9
0.3	7.27E-9	0.3	3.78E-9	0.3	4.04E-9
0.4	6.58E-9	0.4	3.36E-9	0.4	4.31E-9
0.5	4.16E-9	0.5	3.32E-9	0.5	3.85E-9
0.6	4.25E-9	0.6	3.15E-9	0.6	4.04E-9
0.7	6.92E-9			0.7	4.45E-9
0.8	4.85E-9				
0.9	6.81E-9				
1.0	4.73E-9				

Table A13

Average Hydraulic Conductivity of Compacted Illitic Soil

to 0.1% HNO3 Saturated with Pb(NO3)2

Replicate 1		Repl	Replicate 2		icate 3
Pore		Pore		Pore	
Volume	_Ave_K	Volume	Ave K	Volume	Ave K
<0.1	8.14E-9	<.1	7.95E-9	<0.1	5.43E-9
0.1	1.46E-8	0.1	9.62E-9	0.1	9.38E-9
0.2	1.40E-8	0.2	8.36E-9	0.2	9.03E-9
0.3	1.12E-8	0.3	8.35E-9	0.3	9.84E-9
0.4	1.24E-8	0.4	7.00E-9	0.4	9.14E-9
0.5	1.07E-8	0.5	6.42E-8	0.5	1.28E-8
0.6	1.10E-8	0.7	4.66E-8	0.6	2.34E-8
0.7	1.92E-8	0.8	1.04E-7	0.7	7.76E-9
0.8	2.55E-8	0.9	1.21E-7	0.8	1.04E-8
0.9	4.70E-8	1.3	1.40E-7	0.9	8.87E-9
1.0	3.15E-8	1.5	1.88E-7	1.0	7.55E-9
1.1	7.14E-8	1.6	1.64E-7	1.1	3.40E-9
1.3	4.65E-8	2.2	1.70E-7	1.2	5.04E-9
1.4	2.73E-8	2.5	1.87E-7	1.3	1.49E-8
		2.9	1.00E-7		,2 0

Table A14

Average Hydraulic Conductivity of Compacted Illitic Soil
to Acetone Containing Lead Paint Pigment

Replicate 1		Replicate 2		Replicate 3	
Pore		Pore		Pore	
Volume	Ave K	Volume	Ave K	Volume	Ave K
<0.1	5.94E-9	<0.1	1.51E-9		
0.1	4.57E-9	0.1	2.90E-9	0.1	1.13E-8
0.2	4.41E-9	0.2	2.41E-9	0.2	5.72E-9
0.3	4.59E-9	0.3	2.90E-9	0.3	4.65E-9
0.4	4.70E-9	0.4	2.96E-9	0.4	4.22E-9
0.5	5.92E-9	0.5	3.38E-9	0.5	4.72E-9
0.6	5.47E-9	0.6	4.96E-9	0.6	4.51E-9
0.7	1.10E-8	0.7	5.77E-9	0.7	5.40E-9
0.8	9.70E-9	0.8	9.56E-9	8.0	5.73E-9
0.9	7.80E-9	0.9	1.45E-8	0.9	1.00E-8
		1.3	5.23E-8	1.0	1.16E-8
				1.1	7.68E-9

Table A15

Average Hydraulic Conductivity of Compacted Illitic

Soil to Xylene Containing Lead Paint Pigment

Replicate 1		Replicate 2		Replicate 3	
	Pore		Pore		
<u>Ave K</u>	Volume	Ave K	<u>Volume</u>	Ave K	
2.39E-8	<0.1	2.71E-9	<0.1	4.04E-9	
8.66E-8	0.1	1.04E-8	0.1	2.19E-8	
4.03E-8	0.2	1.22E-8	0.2	2.12E-8	
4.60E-8	0.3	1.25E-8	0.3	1.76E-8	
4.07E-8	0.4	9.52E-9	0.4	1.28E-8	
3.81E-8	0.5	8.89E-9	0.5	1.68E-8	
4.49E-8	0.6	9.27E-9	0.6	1.65E-8	
2.98E-8	0.7	8.87E-9	0.7	1.11E-8	
3.50E-8	0.8	8.71E-9	0.8	7.89E-9	
2.82E-8			0.9	8.69E-9	
2.86E-8			1.0	7.16E-9	
2.64E-8			1.1	7.40E-9	
3.14E-8					
3.41E-8					
3.07E-8					
3.21E-8					
3.18E-8					
3.11E-8					
3.07E-8					
2.86E-8					
2.87E-8					
2.59E-8					
	Ave K 2.39E-8 8.66E-8 4.03E-8 4.60E-8 4.07E-8 3.81E-8 4.49E-8 2.98E-8 2.86E-8 2.64E-8 3.14E-8 3.14E-8 3.14E-8 3.14E-8 3.15E-8 3.11E-8 3.11E-8 3.17E-8 3.17E-8 3.17E-8 3.17E-8 3.17E-8 3.17E-8 3.17E-8	Pore Volume 2.39E-8	Pore Volume Ave K 2.39E-8 8.66E-8 0.1 1.04E-8 4.03E-8 4.60E-8 0.2 1.22E-8 4.60E-8 0.4 9.52E-9 3.81E-8 0.6 9.27E-9 2.98E-8 2.86E-8 2.64E-8 3.14E-8 3.11E-8 3.07E-8 2.86E-8 2.86E-8 2.86E-8 2.86E-8 2.87E-8	Ave K Volume Ave K Pore Volume 2.39E-8 <0.1	

Table A16 Average Hydraulic Conductivity of Compacted Kaolinitic Soil to 0.01 N CaSO $_{\rm L}$

Replicate 1		Replicate 2		Replicate 3	
Pore Volume	Ave K	Pore Volume	Ave K	Pore Volume	Ave K
2.0	2.51E-7	0.2	4.84E-8		
0.3	2.87E-7	0.3	2.09E-7	0.4	3.97E-7
0.8	1.59E-7	0.5	1.85E-8	0.5	2.66E-7
0.9	9.32E-8	0.6	6.04E-9	1.0	1.56E-7
1.0	1.48E-8	0.7	5.38E-9	1.1	1.21E-7
1.1	1.76E-9			1.2	1.02E-7
				1.4	8.90E-8
				1.5	6.04E-8

Table A17

Average Hydraulic Conductivity of Compacted Kaolinitic Soil

to Saturated Lead Acetate Solution

Replicate 1		Replicate 2		Replicate 3	
Pore Volume	Ave K	Pore Volume	Ave K	Pore Volume	Ave K
0.6	1.73E-7	0.2	4.90E-8	0.4	9.97E-8
1.0	7.15E-8	0.3	8.75E-9	0.8	9.26E-8
1.3	5.17E-8	0.4	3.77E-9	1.2	5.85E-8
1.5	4.53E-8	0.5	2.6E-10	1.3	3.87E-8
1.6	4.15E-8	0.7	5.42E-7	1.4	3.10E-8
		1.1	1.23E-7		
		1.2	1.01E-7		
		1.5	7.16E-8		
		1.6	9.32E-8		

Table A18

Average Hydraulic Conductivity of Compacted Kaolinitic Soil

to 0.1% HNO3 Saturated with Pb(NO3)2

Replicate 1			cate 2		
Pore Volume	Ave K	Pore <u>Volume</u>	Ave_K	Pore <u>Volume</u>	Ave K
<0.1	1.64E-7				
0.1	1.43E-6				
0.2	9.94E-7	0.2	2.55E-6	0.2	2.85E-6
0.3	7.57E-7	0.3	3.82E-6	0.3	2.29E-6
0.4	5.67E-7	0.4	2.45E-6	0.4	2.03E-6
0.5	5.19E-7	0.5	2.73E-6	0.5	1.97E-6
0.6	3.79E-7	0.6	2.65E-6	0.6	1.82E-6
0.7	3.36E-7	0.7	2.49E-6	0.8	1.55E-6
0.8	3.41E-7	1.0	2.27E-6	0.9	1.37E-6
1.6	2.43E-7	1.1	2.49E-6	1.1	1.32E-6
1.7	1.22E-7	1.2	2.18E-6	1.3	1.16E-6
1.8	9.94E-8	1.5	2.11E-6	1.6	1.15E-6
		1.9	2.03E-6	1.9	1.23E-6
		2.4	1.98E-6	2.2	1.18E-6
		2.9	1.82E-6		
		3.0	1.64E-7		

Table A19

Average Hydraulic Conductivity of Compacted Kaolinitic Soil

to Acetone Containing Lead Paint Pigment

Replicate 1		Replicate 2		Replicate 3		
Pore Volume	Ave K	Pore Ave K Volume Ave K		Pore Volume	Ave K	
<0.1	1.65E-9	<0.1	1.28E-9	<0.1	1.90E-9	
0.1	1.62E-9	0.1	2.22E-9	0.1	2.03E-9	
0.2	1.39E-9	0.2	1.94E-9			

Table A20

Average Hydrualic Conductivity of Compacted Kaolinitic Soil

to Xylene Containing Lead Paint Pigment

Replicate 1		Repli	Replicate 2		Replicate 3	
Pore Volume	Ave K	Pore Volume	Ave K	Pore Volume	Ave K	
<0.1	4.21E-9	<0.1	4.16E-9	<0.1	4.40E-9	
0.1	1.08E-8	0.1	1.13E-8	0.1	7.07E-9	
0.2	1.19E-8	0.2	1.38E-8	0.2	8.14E-9	
0.3	1.18E-8	0.3	1.38E-8	0.3	8.71E-9	
0.4	1.16E-8	0.4	1.45E-8	0.4	8.28E-9	
0.5	1.03E-8	0.5	1.30E-8	0.5	8.16E-9	
0.6	9.66E-9	0.6	1.51E-8	0.6	1.38E-8	
0.7	7.83E-9	0.7	1.31E-8	0.7	8.98E-9	
0.8	8.36E-9	0.8	1.46E-8	0.8	9.51E-9	
0.9	7.12E-9	0.9	1.19E-8	0.9	8.73E-9	
1.0	7.00E-9	1.0	1.36E-8	1.0	1.16E-8	
		1.1	1.42E-8			
		1.2	1.43E-8			
		1.3	1.07E-8			

END

FILMED

12-85

DTIC